BORREGO VALLEY RNAV (GPS) RWY 26

Southern California airport offers desert view on approach

BY JASON BLAIR

O TERRAIN ON THREE SIDES

With initial approach fixes available to the east and southeast of the airport, a pilot will do well to pay attention to elevation in the area. Much of the terrain to the north, west, and south of the approach is rising along the approach path. Keep to the course to avoid encumbering the rocky surfaces that surround the airport.

O STEPDOWNS, NO GLIDESLOPE

Many GPS approaches are WAAS-based and have an LPV minimum published so the pilot will have a glideslope to follow along the approach. Not this one. This is an older-style LNAV MDA Minimum Descent Altitude (MDA) nonprecision

A TRIP TO THE NEARBY Salton Sea, a hike in Slot Canyon, or a rare chance to visit the desert wildflower displays, if you time it right, might take you to this airport in Borrego Springs, California, with one singular GPS approach to Runway 26.

approach. A pilot will have a sequence of descents from the SEDYO waypoint at 3,800 feet, down to 3,100 feet to HAKUR, and then 2,400 feet to the FAF of COMTU before finally descending down to the applicable MDA of 1,720 feet for most aircraft.

G TURN AT FAF Most approaches will

have the aircraft established straight in and then on the same course from the final approach fix (FAF) to the missed approach point. This approach brings a pilot along multiple IAFs, through intermediate fixes, and to the FAF at which point they must turn. A pilot starting this approach at the OCURO waypoint to the east would fly inbound on a 263-degree course, then turn at SEDYO to a 268-degree course, and then turn again to a 250-degree course at the COMTU FAF before turning toward the runway. Be sure not to miss these turns to stay on the published approach procedure.

© CIRCLING LEFT TRAFFIC RUNWAY 8

If a pilot was going to need to land on Runway 8 for wind conditions, a note indicates "Not Authorized South of Rwy 8-26." This would have a pilot fly left traffic for Runway 8, even though on the chart this looks like it would be closer

to terrain than circling to the south of the runway. This is also confusing since the missed approach is a left turn out to the south of the airport, but it is worth noting that the missed starts a mile beyond the runway end.

MISSED U-TURN BACK TO THE EAST

Going missed on this approach would be reguired at the ASIYO waypoint, which is 1 nm from the runway if the runway environment wasn't visible. The missed would take a pilot back out to the OCURO waypoint to hold. Note that this hold is not on the inbound course of 263 degrees but instead on a 257-degree inbound course with right turns for a 4 nm holding leg.

JEPPESEN BORREGO SPRINGS, CALIF LØ8/BXS 3 SEP 21 (12-1) RNAV (GPS) Rwy 26 **BORREGO VALLEY** LOS ANGELES Center (R 126.575 128.6 CTAF 122.8 MDA(H) Apt Elev 522' RNAV Apch Crs 1720'(1200') 2400'(1880') TDZE 520' 250° 10,000 MISSED APCH: Climbing LEFT turn to 4000' direct OCURO and hold. RNP Apch-GPS Alt Set: INCHES Trans level: FL 180 Trans alt: 18000 1. Use local altimeter setting; if not received, use Imperial Co altimeter setting. 2. VDP not authorized with Imperial Co altimeter setting. 3. VGSI and descent angles MSA ASIYO not caincident. 4. Pilot controlled lighting 122.8. ASIYO _250° COMTU 268°, SEDYO HAKUR OCURO 1188 R-2510A/B SEDYO HAKUR 3800 COMTU 3100 TCH 421 TDZE 520 Gnd speed-Kts 70 90 100 120 140 160 Descent Angle 3.46* 429 551 612 735 857 980 -D-OCURO iT MAP at ASIYO STRAIGHT-IN LANDING RWY 26 CIRCLE-TO-LAND Not Authorized South of Rwy 8-25 With Local Altimeter Setting With Imperial Co Altimeter Setting MDA(H) 2300'(1780') MDA(H) 1720'(1200') 1720(1198') -1/4 2300'(1778') -1/4 11/4 11/2 120 1720 (1198) - 1/2 2300 (1778) - 1/2 1/2 1840'(1318') -3 2420'(1898') -3 CHANGES: Comms, airport alex, notes, topo, circling minimums, chart format. 👸 JEPPESIN, 2003, 2021. ALL RIGHTS RESERVED.

JASON BLAIR is a flight instructor, FAA examiner, and author in the general aviation and training communities.

0 21